Mail completed form to:

PUBLIC UTILITIES COMMISSION 500 EAST CAPITOL AVENUE PIERRE, SD 57501 ATTN: SOUTH DAKOTA ONE CALL BOARD

Nov 1 3 2006

RECEIVED

SOUTH DAKOTA PUBLIC UTILITIES COMMISSION

ALLEGATION OF PROBABLE VIOLATION(S) OF SOUTH DAKOTA ONE CALL LAWS

I. ACTION REQUESTED BY:
COMPLAINT FILED BY INDIVIDUAL OR BUSINESS* PERSON FILING COMPLAINT: Wayne Fletcher
COMPANY: City of Brandon ADDRESS: 304 main Ave. PO Box 95 PHONE NUMBER: 605-582-3373
SIGNATURE OF COMPLAINANT: DATE: 11-09-06 EMAIL ADDRESS: wfletcher@cityofbrandon.org
*If the complaint is files on behalf of a Company, the person signing this form should have the proper authority to file the complaint.
II. ACTION REQUESTED AGAINST:
NAME OF EXCAVATOR/FACILITY OPERATOR: Jeremy Scadden Construction PHONE NUMBER: 605-757-6616
ADDRESS: 120 Olson St. Valley Springs, SD. 57068
WAS A LOCATE REQUESTED FROM SD ONE CALL? YES NO NO LOCATE TICKET #: NONE
START DATE ON TICKET: <u>NONE</u>
DID EXCAVATOR WAIT UNTIL THE START DATE/TIME ON THE TICKET BEFORE COMMENCING EXCAVATION? YES NO N/A 🖂
WERE BURIED FACILITIES EXPOSED BY HAND OR WITH NON-INVASIVE EQUIPMENT PRIOR TO EXCAVATION? YES ☐ NO ☐ N/A ⊠
III. FACILITY INVOLVED (IF ANY)
TYPE OF FACILITY INVOLVED: OPERATOR OF FACILITY (IF KNOWN):
OPERATOR ADDRESS: PHONE NUMBER:
DEPTH OF COVER: PRESSURE: VOLTAGE: NUMBER OF CABLE PAIRS:
IV. MARKING
WERE FACILITIES MARKED? YES ☐ NO ☒ N/A ☐
WAS THE MARKING COMPLETE PRIOR TO THE START TIME ON THE TICKET? YES \Box NO \boxtimes N/A \Box
DID EXCAVATOR PRE-MARK WITH WHITE PAINT? YES NO N/A
WAS THE FACILITY MARKED ACCURATELY (WITHIN 18 INCHES)? YES ☐ NO ☐ N/A ☒
DID EXCAVATOR USE REASONABLE CARE TO MAINTAIN LOCATE MARKS FOR LIFE OF PROJECT? YES NO
HAVE YOU DISCUSSED THE PREVIOUS STATEMENTS WITH THE OTHER PARTY? YES ☐ NO ☒

V. DAMAGE (IF ANY) FATALITIES: INJURIES: LENGTH OF HOSPITALIZATION: ESTIMATED PROPERTY DAMAGE (\$): NUMBER OF CUSTOMERS AFFECTED: DAMAGED IN: PUBLIC PRIVATE (RIGHT-OF-WAY) PHOTOS OF THE DAMAGED FACILITY? YES NO ADDITIONAL INFORMATION: VI. PROBABLE VIOLATION SPECIFIC STATUE(S) OR RULE(S) THAT WAS VIOLATED: 49-7A-5
ESTIMATED PROPERTY DAMAGE (\$): NUMBER OF CUSTOMERS AFFECTED: DAMAGED IN: PUBLIC PRIVATE (RIGHT-OF-WAY) PHOTOS OF THE DAMAGED FACILITY? YES NO ADDITIONAL INFORMATION: VI. PROBABLE VIOLATION
DAMAGED IN: PUBLIC PRIVATE (RIGHT-OF-WAY) PHOTOS OF THE DAMAGED FACILITY? YES NO ADDITIONAL INFORMATION: VI. PROBABLE VIOLATION
PHOTOS OF THE DAMAGED FACILITY? YES NO NO ADDITIONAL INFORMATION: VI. PROBABLE VIOLATION
ADDITIONAL INFORMATION: VI. PROBABLE VIOLATION
VI. PROBABLE VIOLATION
CDECIEIC CTATUE/C) OD DIU E/C) THAT WAS VIOLATED: 40.74.5
STECIFIC STATUE(S) OR RULE(S) THAT WAS VIOLATED: 45-7A-3
ADDRESS/LOCATION OF PROBABLE VIOLATION: 205 Fairway Ave., Brandon, SD 57005
DATE/TIME OF PROBABLE VIOLATION: work done between 10-1-06 & 11-08-06
HAVE YOU DISCUSSED THIS PROBABLE VIOLATION WITH THE PARTY THE ACTION IS FILED
AGAINST: YES □ NO ☑
IF YES, NAME OF THE PARTY WITH WHOM YOU DISCUSSED THE PROBABLE VIOLATION:
DESCRIPTION OF PROBABLE VIOLATION: No one call made and the excavator has disturbed soil on this lot







